



BE-9882S

ergo®



НАБОРЫ ОТВЕРТОК

- Набор отверток ERGO™ с изоляцией, 5 штук
- Под винты со шлицем и Pozidriv
- В картонной коробке

| | | | |
|----------|-------------------|---|-------|
| | | | |
| BE-9882S | 731415 1839314 | 1 | 450 g |

BE-8220S, BE-8040S, BE-8050S
0.5x3x100, 0.8x4x100, 1x5.5x125



BE-8810S, BE-8820S
PZ1x80, PZ2x100



BE-9888S

ergo®



НАБОРЫ ОТВЕРТОК

- Набор отверток ERGO™ с изоляцией, 7 штук
- Под винты со шлицем и Pozidriv
- В картонной коробке

| | | | |
|----------|-------------------|---|-------|
| | | | |
| BE-9888S | 731415 3006158 | 1 | 530 g |

BE-8010S, BE-8220S, BE-8040S, BE-8050S
0.4x2.5x75, 0.5x3.0x100, 0.8x4.0x100, 1.0x5.5x125



BE-8800S, BE-8820S, BE-8830S
PZ0x75, PZ2x100, PZ3x150



BE-9885S

ergo®



НАБОРЫ ОТВЕРТОК

- Набор комбинированных отверток ERGO™ с изоляцией, 4 штуки (8 насадок) и тестер напряжения
- Под винты со шлицем, Pozidriv и Phillips
- В картонной коробке

| | | | |
|----------|-------------------|---|-------|
| | | | |
| BE-9885S | 731415 0126491 | 1 | 445 g |

806-1-1
0.6x3x65



BE-8510S, BE-8520S
5/PH1, 6/PH2



BE-8710S, BE-8720S
5/PZ1, 6/PZ2

